

Golden Rules

PPE

Fitness for Work

Plant & Equipment

Hard Hat



Worn correctly, not backwards, only approved liners underneath

Safety Glasses



Must conform to Australian Standards. Double eye protection required for grinders & demo saw operations

Fatigue Management



10 hour breaks between shifts must be applied

Authorisation



Only licensed & competent persons to operate plant

Maintenance



All plant faults and required maintenance to be reported

Clothing



Long sleeve, high vis top, steel capped boots, gloves worn or on carry clip at all times

Sun Smart



Wear sunscreen, use brims for hard hats

Drugs & Alcohol



Consumption, impairment, possession or sale of alcohol or illicit drugs is strictly prohibited

No Smoking



No smoking in ACE / hire vehicles, plant or buildings

Operating Zones



Never approach operating equipment unless positive communication with operator

Operations

Trenching Entry



Entry to trenches 1.5m or greater require shoring. No working outside shoring. No person may enter a trench >1.0m unless it is benched, battered or shoring in place

Electrocution Hazard



Power poles/lines
3 - 6.4m spotter required
<3m No Go Zone

SWMS



All High Risk Activities to have a SWMS, must be signed & followed as documented

Incidents



All incidents & near misses must be reported to the site supervisor

ents Environment



You must not enter a Tree Protection Zone / No Go Zone without approval from Supervisor & Work Method Statement

Inground Services



Spotters required when working in vicinity to underground infrastructure - ref to excavation permit.

Excavation Permit



Breaking ground or penetration of surface prohibited without a completed permit

Working at Heights



When working at 2 meters or greater fall protection must be used

No Headphones



People must not wear ear buds (music, phone etc) or noise cancelling headphones

Water Quality



Outfalls must be protected with sediment controls to prevent site runoff leaving site and entering local waterways







